

M850-MP1



Lets set the unit to the following:
Maximum Demand time to 30 minutes

1. Press I & E together for 5 seconds
2. Press E—twice until you see dt
3. Press I—this will show you rset (reset)
4. Press I—to reset any value that may already have been logged
5. Press I to reset
6. Press E not to reset
7. Press E which will now show dtst (damand time setting)
8. Press I—this will show what is currently set in minutes
9. This will show what the meter is set to, keep pressing E until you get 0
10. Press I to move to the next digit
11. Press E three times to change the 0 to 3
12. Press I to return to dtst
13. Press E this will allow you to cancel any settings or
14. Press E to go to confirm screen
15. Press I to confirm the setting
16. Press E five times to get to end
17. Press I to come out of settings

SUPP
485
dt
rSEt

y n

rSEt

dtSt

3

0

00

30

dtSt

cncl

conf

dt

End

Please note that this unit can has the capacity to be set
Up to 60 minutes in steps of 1 minutes.

If no buttons are pressed for some time then the unit will
jump out of the setting mode.

